

Material Safety Data Sheet

Date Prepared November 10, 2006

Identification

Product Name: **“Summit”**

Supplier Name : TORLYS Inc., 1900 Derry Road East, Mississauga, Ontario L5S 1Y6
Ph: 800 461-2573
Fx: 800 461-5220

Description: A plywood panel product manufactured with wood species like Red Oak or European Maple as top layers bonded with resin by hot press.

Hazardous Ingredients

#1 Identification: Formaldehyde

Exposure Limits: ACGIH Limit = 1 ppm 8-hr TWA 2 ppm STEL
OSHA Limit = 1 ppm 8-hr TWA 2 ppm STEL

Formaldehyde Emmissions: Avg PPM 0.04 per ASTM E1333

#2 Identification: Wood Dust

Exposure Limits: OSHA PEL-TWA 5mg/rn3
OSHA PEL-STEL 10mg/m3

Potential Airborne Releases: Manual or mechanical cutting or abrasion processes performed on the product can result in the generation of wood dust.

#3 Identification: Ceramic Coating

Exposure Limit: Unknown

Emissions: Unknown

Physical Characteristics

Boiling Point: N/A

Specific Gravity (H2O=1): Less than 1

Vapor Pressure: N/A

Melting Point: N/A

Vapor Density: N/A

Reactivity in Water: N/A

Evaporation Rate: N/A

Appearance: Varies by Species and stain color

TORLYS

smart floors

Fire and Explosion Data

Flash Point:	N/A
Auto Ignition Temperature:	425 Degrees to 475 Degrees
Explosive Limits In Air:	The product listed in this MSDS is not an explosion hazard. Sawing, Sanding, or Machining could result in the by-product wood dust. Wood dust may present a strong to severe explosion hazard if a dust cloud contacts an ignition source.
Fire Extinguishing Media:	Water, Carbon Dioxide, Sand
Special Fire Fighting Procedures:	Fire fighting procedures for wood are well known.

Health Hazard Data

1.1 Formaldehyde Vapor / Signs and Symptoms of Exposure:

Acute=May cause temporary irritation of skin, eyes, or respiratory systems. May cause Sensitization in susceptible individuals.

Chronic=Numerous epidemiological studies have failed to demonstrate a relationship between Formaldehyde exposure and nasal cancer or pulmonary diseases such as emphysema or lung Cancer. UAREP concluded that there was no "Convincing Evidence" that formaldehyde exposure causes cancer in humans. Rats exposed to 14ppm of formaldehyde for 24 months in a laboratory developed nasal cancer. Exposure of 6ppm did not result in statistically significant levels. The NCI epidemiology study of 26,000 workers found little evidence linking formaldehyde exposure to cancer. Formaldehyde is classified by OSHA, NTP and IARC as a probable or potential carcinogen.

1.2 Medical conditions Aggravated by

Formaldehyde exposure: Respiratory conditions or allergies

1.3 Emergency First Aid Procedures:

Inhalation: Remove to fresh air

Eyes: Remove to fresh air

Skin: Remove to fresh air

Ingestion: N/A

If irritation or other symptoms persist, consult a physician.

2.1 Wood Dust

Eye Contact: Wood Dust can cause mechanical irritation

Skin Contact: Various species of wood dust may evoke allergy in sensitive individuals

Ingestion: Not likely to occur

Burning: According to ISO/DIS 5660 tests, the toxicity index of fire effluents was small, but there are many compounds in smoke oases which can cause irritation to eyes, nose & throat.

Inhalation of wood dust: Wood dust may cause nasal dryness, irritation and obstruction.

Coughing, wheezing and sneezing: sinusitis and prolonged colds have also been reported.

Depending on species, wood dust may cause dermatitis on prolonged, repetitive contact; may cause respiratory sensitization and/or irritation. IARC classifies wood dust as a carcinogen to human (Group 1).

TORLYS

smart floors

This classification is based primarily on IARC's evaluation of increased risk in the occurrence of aden carcinomas of the nasal cavities and para nasal sinuses associated with the exposure to wood dust. IARC did not find sufficient evidence to associate cancer of the oropharynx, hypo pharynx, lung, lymphatic and hematopoietic systems, stomach, colon or rectum with exposure to wood dust.

Wood Dust classification from ACGIH: Hard Woods and Softwoods (non-allergenic); "A4 irritation, mucostasis" except Birch and Oak.

2.2 Emergency and First Aid Procedures:

Eye contact: Flush eyes with large amounts of water. Enable fresh air environment. If irritation persists, get medical attention.

Skin contact: Wash affected areas with soap and water. Get medical advice if rash or persistent irritation or dermatitis occurs.

Inhalation: Remove to fresh air. Get medical advice if persistent irritation, severe coughing or breathing difficulty occurs.

Ingestion: Not applicable

Reactivity Data

Conditions contributing To Instability: Stable under normal conditions

Incompatibility: Avoid contact with oxidizing agents & strong acids. Avoid open flame. Product may ignite in excess of 425 ° Celsius.

Hazardous decomposition Products: Thermal and/or thermal-oxidative decomposition can produce irritating and toxic fumes and Gases, including carbon monoxide, aldehydes and organic acids.

Hazardous polymerization: N/A

Precautions, Safe Handling

Handling and Storage: There may be a buildup of noxious gases in temperatures higher than 212 ° Celsius. Provide adequate ventilation to reduce the possible buildup of formaldehyde vapors above OSHA PEL's.

Personal Protective Equipment: Wear goggles or safety glasses when manufacturing or machining the product. Wear NIOSH/MSHA approved respirator when allowable exposure limits may be exceeded. Other protective equipment such as gloves and outer garments may be needed depending on dust conditions.

Waste Disposal Method: Incinerate or landfill in accordance with local, state and federal regulations.

TORLYS


smart floors

Important-Disclaimer

The information and data herein are believed to be accurate and have been compiled from sources believed to be reliable. TORLYS Inc. makes no warranty of any kind, expressed or implied, concerning the accuracy or completeness of the information and data herein. TORLYS Inc. will not be liable for claims relating to any party's use of or reliance on information and data contained herein regardless of whether it is claimed that the information and data are inaccurate, incomplete or otherwise misleading. It is offered for your consideration, investigation and verification. Due to possible technical changes it is incumbent upon the user to obtain the most up to date information.

 **Torlys National Call Centre Location**
1900 Derry Road E., Mississauga, ON L5S 1Y6

PH: 905-612-8772 800-461-2573
FAX: 905-612-9049 800-461-5220

 **Torlys British Columbia Location**
1292 Cliveden Avenue, Delta, British Columbia,
V3M 6G4 Canada

PH: 604-777-9744
FAX: 604-777-9766